

75 POINT INSPECTION

MAGNUM MACHINE

106-B Tranquille Road, Kamloops, BC, V2B 3E7
Ph: 250-376-1186 Fax: 250-376-1821

WO#: _____

License #: _____

Advisor: Corey

NAME: Auberman ADDRESS: VIN# 1C3ES46C4Y0628029
YEAR: 2000 MAKE: Chrysler Neon STOCK #: _____ KILOMETRES: 98,916

S = Satisfactory P = Postponable NS = NOT SATISFACTORY

NOTE: This report indicates the condition of the vehicle only as of the date indicated above and is based on a visual inspection only as aided by instruments. No opinion is offered and no responsibility can be accepted for defects or conditions which may be discovered by dismantling of components or parts whether or not included in this inspection or hidden by body work, paint, or undercoat. This report is for your information only and is not a warranty or guarantee for any purpose and the dealer assumes no liability whatsoever in respect thereof.

LIGHTS	S	P	NS
Headlights - left	✓		
Headlights - right	✓		
Park / Tail	✓		
High Mount Light	✓		
Stop	✓		
Turn Signals	✓		
License	✓		
Marker	✓		

MISCELLANEOUS	S	P	NS
Glass Condition	✓		
Windshield Wipers	✓		
Windshield Washer	✓		
Horn	✓		

DRIVE SHAFT	S	P	NS
U Joints: Front			
Centre	N/A		
Rear	N/A		
CV Joints / Boots	✓		

REAR AXLE	S	P	NS
Pinion Seal	✓		

SUSPENSION / STEERING	S	P	NS
Springs	✓		
Shocks: Front (left)	✓		
Shocks: Front (right)	✓		
Tie Rods: inner	✓		
Tie Rods: outer	✓		
Ball Joints: left	✓		
Ball Joints: right	✓		
Centre Link			
Idling Arm	N/A		
Steering Box	✓		
Power Steering: Pump / Reservoir	✓		
Power Steering: Hoses	✓		
Belt Condition	✓		
Alignment - visual only	✓		

TIRES
Front Tires: LS <u>60</u> % remaining RS <u>50</u> % remaining
Rear Tires: LS <u>40</u> % remaining RS <u>40</u> % remaining
Pressure (psi): RF <u>35</u> LF <u>35</u> RR <u>35</u> LR <u>35</u>

Technician Comments: New Battery

SUSPENSION - REAR	S	P	NS
Springs	✓		
Shocks: left	✓		
Shocks: right	✓		

EXHAUST SYSTEM	S	P	NS
Front Pipe	✓		
Catalytic Converter	✓		
Muffler	✓		
Centre Pipe	✓		
Rear Pipe	✓		
Brackets	✓		

BRAKE SYSTEM	S	P	NS
Brake Fluid Level	✓		
Hoses and Lines	✓		

BRAKE - front	S	P	NS
Rotor <input checked="" type="checkbox"/> Drum <input type="checkbox"/>			
Left Brake <u>70</u> % remaining	✓		
Right Brake <u>70</u> % remaining	✓		

BRAKE - rear	S	P	NS
Rotor <input type="checkbox"/> Drum <input checked="" type="checkbox"/>			
Left Brake <u>60</u> % remaining	✓		
Right Brake <u>60</u> % remaining	✓		

TEST DRIVE	S	P	NS
Engine	✓		
Clutch	✓		
Transmission	✓		
Steering	✓		
Brakes	✓		

ENGINE	S	P	NS
Oil Leaks: pan	✓		
Oil Leaks: main seal	✓		
Oil Leaks: valve cover	✓		
Oil Leaks: timing cover	✓		
Engine Mounts	✓		

ENGINE COOLING	S	P	NS
Hoses	✓		
Belt Condition	✓		
Water Pump	✓		
Coolant Good To: <u>-45°C</u>	✓		

TRANSMISSION SYSTEM	S	P	NS
Oil Leaks	✓		

MISCELLANEOUS	S	P	NS
Doors - Lubed	✓		
Trunk - Clean	✓		
Spare Tire	✓		
Jack & Tools	✓		
Windows & Locks	✓		
Mag Wheel Key Location: <u>Glovebox</u>	✓		