

# 75 POINT INSPECTION



## MACHINE & AUTOMOTIVE

ENGINES • DRIVELINES • AUTO REPAIRS

106-B Tranquille Road, Kamloops, BC, V2B 3E7  
Ph: 250-376-1186 Fax: 250-376-1821

WO#: R10399  
License #: \_\_\_\_\_  
Advisor: Corey

NAME: Autorama VIN: 3G1JC52F743179414  
YEAR: 2004 MAKE: Chev MODEL: Cavalier KILOMETRES: 131,455

**S = Satisfactory P = Postponable NS = NOT SATISFACTORY**

NOTE: This report indicates the condition of the vehicle only as of the date indicated above and is based on a visual inspection only as aided by instruments. No opinion is offered and no responsibility can be accepted for defects or conditions which may be discovered by dismantling of components or parts whether or not included in this inspection or hidden by body work, paint, or undercoat. This report is for your information only and is not a warranty or guarantee for any purpose and the dealer assumes no liability whatsoever in respect thereof.

LIGHTS	S	P	NS
Headlights - left	/		
Headlights - right	/		
Park / Tail	/		
High Mount Light	/		
Stop	/		
Turn Signals	/		
License	/		
Marker	/		
MISCELLANEOUS			
Glass Condition	/		
Windshield Wipers	/		
Windshield Washer	/		
Horn	/		
DRIVE SHAFT			
U Joints: Front			
Centre	N/A		
Rear	N/A		
CV Joints / Boots	/		
REAR AXLE			
Pinion Seal	/		
SUSPENSION / STEERING			
Springs	/		
Shocks: Front (left)	/		
Shocks: Front (right)	/		
Tie Rods: inner	/		
Tie Rods: outter	/		
Ball Joints: left	/		
Ball Joints: right	/		
Centre Link	N/A		
Idling Arm	/		
Steering Box	/		
Power Steering: Pump / Reservoir	/		
Power Steering: Hoses	/		
Belt Condition	/		
Alignment - visual only	/		
TIRES			
Front Tires: LS <u>40</u> % remaining RS <u>40</u> % remaining			
Rear Tires: LS <u>40</u> % remaining RS <u>40</u> % remaining			
Pressure (psi): RF <u>30</u> LF <u>30</u> RR <u>30</u> LR <u>30</u>			

SUSPENSION - REAR	S	P	NS
Springs	/		
Shocks: left	/		
Shocks: right	/		
EXHAUST SYSTEM			
Front Pipe	/		
Catalytic Converter	/		
Muffler	/		
Centre Pipe	/		
Rear Pipe	/		
Brackets	/		
BRAKE SYSTEM			
Brake Fluid Level	/		
Hoses and Lines	/		
BRAKE - front			
Rotor <input checked="" type="checkbox"/> Drum <input type="checkbox"/>	/		
Left Brake <u>100</u> % remaining	/		
Right Brake <u>100</u> % remaining	/		
BRAKE - rear			
Rotor <input type="checkbox"/> Drum <input checked="" type="checkbox"/>	/		
Left Brake <u>30</u> % remaining	/		
Right Brake <u>30</u> % remaining	/		
TEST DRIVE			
Engine	/		
Clutch	N/A		
Transmission	/		
Sterring	/		
Brakes	/		
ENGINE			
Oil Leaks: pan	/		
Oil Leaks: main seal	/		
Oil Leaks: valve cover	/		
Oil Leaks: timing cover	/		
Engine Mounts	/		
ENGINE COOLING			
Hoses	/		
Belt Condition	/		
Water Pump	/		
Coolant Good To: <u>-45°C</u>	/		
TRANSMISSION SYSTEM			
Oil Leaks	/		
MISCELLANEOUS			
Doors - Lubed	/		
Trunk - Clean	/		
Spare Tire	/		
Jack & Tools	/		
Windows & Locks	/		
Mag Wheel Key Location: <u>NONE</u>			

Technician Comments: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_