

80 POINT VEHICLE INSPECTION



MACHINE & AUTOMOTIVE
ENGINES • DRIVELINES • AUTO REPAIRS

106-B Tranquille Road, Kamloops, BC, V2B 3E7
 Ph: 250-376-1186 Fax: 250-376-1821

WO#: R11550
 Advisor: Corey

NAME: Autorama Vehicle Sales VIN: 5N1BV28U84N317977
 YEAR: 2004 MAKE: Nissan MODEL: Quest KILOMETRES: 134,467

S = Satisfactory P = Postponable NS = NOT SATISFACTORY

NOTE: This report indicates the condition of the vehicle only as of the date indicated above and is based on a visual inspection only as aided by instruments. No opinion is offered and no responsibility can be accepted for defects or conditions which may be discovered by dismantling of components or parts whether or not included in this inspection or hidden by body work, paint, or undercoat. This report is for your information only and is not a warranty or guarantee for any purpose and the dealer assumes no liability whatsoever in respect thereof.

LIGHTS	S	P	NS
Headlights - left	X		
Headlights - right	X		
Park / Tail	X		
High Mount Light	X		
Stop	X		
Turn Signals	X		
License	X		
Marker	X		
MISCELLANEOUS			
Glass Condition	X		
Windshield Wipers	X		
Air Cleaner	X		
Horn	X		
DRIVE SHAFT			
U Joints: Front	N/A		
Centre	N/A		
Rear	N/A		
CV Joints / Boots	X		
REAR AXLE			
Pinion Seal	N/A		
SUSPENSION / STEERING			
Springs	X		
Shocks: Front (left)	X		
Shocks: Front (right)	X		
Tie Rods: inner	X		
Tie Rods: outer	X		
Ball Joints: left	X		
Ball Joints: right	X		
Centre Link	N/A		
Idling Arm	N/A		
Steering Box	X		
Power Steering: Pump / Reservoir	X		
Power Steering: Hoses	X		
Belt Condition	X		
Alignment - visual only	X		
4x4 - AWD SYSTEM			
Transfer Case	N/A		
4WD System Engages	yes:	no: N/A	
CHARGING SYSTEM			
Battery	X		
Alternator	X		
TIRES			
Front Tires: LS 60 % remaining. RS 60 % remaining			
Rear Tires: LS 60 % remaining RS 60 % remaining			
PSI: 30 Type: 215/65/16 - All Season			

SUSPENSION - REAR	S	P	NS
Springs	X		
Shocks: left	X		
Shocks: right	X		
EXHAUST SYSTEM			
Front Pipe	X		
Catalytic Converter	X		
Muffler	X		
Centre Pipe	X		
Rear Pipe	X		
Brackets	X		
BRAKE SYSTEM			
Fluid, Hoses, Lines	X		
Emergency Brake System	X		
BRAKE - front			
Rotor <input checked="" type="checkbox"/> Drum <input type="checkbox"/>	X		
Left Brake: 100 % remaining	X		
Right Brake: 100 % remaining	X		
BRAKE - rear			
Rotor <input checked="" type="checkbox"/> Drum <input type="checkbox"/>	X		
Left Brake: 100 % remaining	X		
Right Brake: 100 % remaining	X		
TEST DRIVE			
Engine	X		
Clutch	N/A		
Transmission	X		
Steering	X		
Brakes	X		
ENGINE			
Oil Leaks: pan	X		
Oil Leaks: main seal	X		
Oil Leaks: valve cover	X		
Oil Leaks: timing cover	X		
Engine Mounts	X		
ENGINE COOLING			
Hoses	X		
Belt Condition	X		
Water Pump	X		
Coolant Good To: -45 C - PH Level: 7.0			
TRANSMISSION SYSTEM			
Oil Leaks	X		
MISCELLANEOUS			
Doors - Lubed	X		
Trunk - Clean	X		
Spare Tire	X		
Jack & Tools	X		
Windows & Locks	X		
Mag Wheel Key Location:	N/A		