

# 75 POINT VEHICLE INSPECTION



**MACHINE & AUTOMOTIVE**  
ENGINES • DRIVELINES • AUTO REPAIRS

106-B Tranquille Road, Kamloops, BC, V2B 3E7  
Ph: 250-376-1186 Fax: 250-376-1821

WO#: R11504  
Advisor: Mike

NAME: Autorama VIN: 3FAFP07Z86R191885  
YEAR: 2006 MAKE: Ford MODEL: Fusion KILOMETRES: 90,332.1

**S = Satisfactory P = Postponable NS = NOT SATISFACTORY**

NOTE: This report indicates the condition of the vehicle only as of the date indicated above and is based on a visual inspection only as aided by instruments. No opinion is offered and no responsibility can be accepted for defects or conditions which may be discovered by dismantling of components or parts whether or not included in this inspection or hidden by body work, paint, or undercoat. This report is for your information only and is not a warranty or guarantee for any purpose and the dealer assumes no liability whatsoever in respect thereof.

LIGHTS	S	P	NS
Headlights - left	✓		
Headlights - right	✓		
Park / Tail	✓		
High Mount Light	✓		
Stop	✓		
Turn Signals	✓		
License	✓		
Marker	✓		
<b>MISCELLANEOUS</b>			
Glass Condition	✓		
Windshield Wipers	✓		
Windshield Washer	✓		
Horn	✓		
<b>DRIVE SHAFT</b>			
U Joints: Front	N/A		
Centre	N/A		
Rear	N/A		
CV Joints / Boots	N/A		
<b>REAR AXLE</b>			
Pinion Seal	N/A		
<b>SUSPENSION / STEERING</b>			
Springs	✓		
Shocks: Front (left)	✓		
Shocks: Front (right)	✓		
Tie Rods: inner	✓		
Tie Rods: outer	✓		
Ball Joints: left	✓		
Ball Joints: right	✓		
Centre Link	✓		
Idling Arm	N/A		
Steering Box	✓		
Power Steering: Pump / Reservoir	✓		
Power Steering: Hoses	✓		
Belt Condition	✓		
Alignment - visual only	✓		
<b>TIRES</b>			
Front Tires: LS 80 % remaining. RS 80 % remaining			
Rear Tires: LS 60 % remaining RS 60 % remaining			
Pressure (psi): RF 34 LF 34 RR 34 LR 34			

SUSPENSION - REAR	S	P	NS
Springs	✓		
Shocks: left	✓		
Shocks: right	✓		
<b>EXHAUST SYSTEM</b>			
Front Pipe	✓		
Catalytic Convertor	✓		
Muffler	✓		
Centre Pipe	✓		
Rear Pipe	✓		
Brackets	✓		
<b>BRAKE SYSTEM</b>			
Fluid, Hoses, Lines	✓		
Emergency Brake System	✓		
<b>BRAKE - front</b>			
Rotor <input checked="" type="checkbox"/> Drum <input type="checkbox"/>	✓		
Left Brake: 100 % remaining	✓		
Right Brake: 100 % remaining	✓		
<b>BRAKE - rear</b>			
Rotor <input checked="" type="checkbox"/> Drum <input type="checkbox"/>	✓		
Left Brake: 60 % remaining	✓		
Right Brake: 60 % remaining	✓		
<b>TEST DRIVE</b>			
Engine	✓		
Clutch	N/A		
Transmission	✓		
Steering	✓		
Brakes	✓		
<b>ENGINE</b>			
Oil Leaks: pan	✓		
Oil Leaks: main seal	✓		
Oil Leaks: valve cover	✓		
Oil Leaks: timing cover	✓		
Engine Mounts	✓		
<b>ENGINE COOLING</b>			
Hoses	✓		
Belt Condition	✓		
Water Pump	✓		
Coolant Good To: -35°C C-PH Level: 7.0			
<b>TRANSMISSION SYSTEM</b>			
Oil Leaks	✓		
<b>MISCELLANEOUS</b>			
Doors - Lubed	✓		
Trunk - Clean	✓		
Spare Tire	✓		
Jack & Tools	✓		
Windows & Locks	✓		
Mag Wheel Key Location: N/A			

NEW  
NEW  
NEW

Tech Comments

